

NEW YORK AND EASTERN DIVISION TIMETABLE No. 4, DECEMBER 31, 1904

NORTHERN LIGHTS SUBDIVISION

NORTHWARD												MP Location	SOUTHWARD													
THIRD CLASS					SECOND CLASS			FIRST CLASS					FIRST CLASS		SECOND CLASS				THIRD CLASS							
X Fight	141 Coke	131 Coal	121 Coal	111 Coal	101 Coal	25 Pass	23 Pass	21 Pass	11 Fight	3 Pass	1 Pass		STATIONS	2 Pass	4 Pass	52 Fight	22 Pass	24 Pass	26 Pass	102 Fight	112 Coal	122 Coal	132 Coal	142 Coke	X Fight	
Leave Daily AM	Leave Daily PM	Leave Daily AM	Leave Daily PM	Leave Daily AM	Leave Daily AM	Leave Daily PM	Leave Daily AM	Leave Daily AM	Leave Daily AM	Leave Daily PM	Leave Daily AM		Arrive Daily AM	Arrive Daily PM	Arrive Daily AM	Arrive Daily AM	Arrive Daily PM	Arrive Daily PM	Arrive Daily AM	Arrive Daily AM	Arrive Daily PM	Arrive Daily PM	Arrive Daily PM	Arrive Daily AM		
00:00	08:30	11:39	12:20	00:15	03:15				04:00			0	YL TO R WILLIAMSPORT YARD EAST DEPART			07:55			05:33	04:39	02:49	03:08	10:33	01:21		
						08:15	11:00	01:31		03:45	07:10	0	TO R WILLIAMSPORT STATION DEPART	10:09	06:54		04:54	02:29	11:39							
00:01												4.1 (1.5)												01:20		
00:02												5.6												01:19		
00:04												15.6												01:17		
00:20	09:00	11:59	12:40	00:35	03:35	08:25	11:10	01:41	#112- 04:12	03:54	07:19 #52- 07:29	37 43.5	TO R DEPART	XINA PASS DEPART	10:00 09:50	06:45 06:35	07:45 #1- 07:16	04:44 04:34	02:19 #122- 02:09	11:29 11:19	05:08	04:14 #11- 04:02	02:24 #24- 01:48	02:43	10:08	01:11
00:23	09:03		12:43		03:38							51.4	S	QUILLY MINE #1							05:00		01:45	10:00	00:58	
00:24 00:34		12:13		00:49		08:39 08:49	11:24 11:34	01:55 02:05	04:15 #22- 04:25	04:06 04:16	07:31 07:41	58.4	TO DEPART	BECS BEND DEPART	09:48 09:38	06:33 06:23	07:12 07:02	04:30 #11- 04:20	02:05 01:55	11:15 11:05		03:52		02:33	00:57 00:47	
00:42 00:52		12:31		01:07		08:57 09:07	11:42 11:52	02:13 02:23	04:31 04:41	04:21 04:31	07:46 07:56	76.4	TO DEPART	JAMES CREST DEPART	09:33 09:23	06:18 06:08	06:54 06:44	04:12 04:00	01:47 01:37	10:57 10:47		03:26		02:07	00:39 00:29	
00:52												78.2 -1.5	S	MICHELLE COVE										00:29		
01:01		12:40		01:16								99.2	S	QUILLY MINE #2							03:04		01:45	00:20		
01:02 01:12						09:17 09:27	12:02 12:12	02:33 02:43	04:49 05:29	04:38 04:48	08:03 08:13	103.2	TO DEPART	STANS KNOB DEPART	09:16 09:06	06:01 05:51	06:34 06:24	03:50 03:40	01:27 01:17	10:37 10:27					00:19 00:09	
01:16												112.2 118.2		QUILLY MINE #3										00:05		
01:19												128.1		TIMBER LTD										00:02		
01:21						09:36	12:21	02:52	05:36	04:54	08:19	135	TO R	HIGH CRUST DEPART	09:00	05:45	06:15	03:31	01:08	10:18				00:00		
AM Arrive Daily	PM Arrive Daily	PM Arrive Daily	PM Arrive Daily	AM Arrive Daily	AM Arrive Daily	PM Arrive Daily	PM Arrive Daily	AM Arrive Daily	AM Arrive Daily	PM Arrive Daily	AM Arrive Daily			AM Leave Daily	PM Leave Daily	AM Leave Daily	AM Leave Daily	PM Leave Daily	PM Leave Daily	AM Leave Daily	AM Leave Daily	PM Leave Daily	PM Leave Daily	PM Leave Daily	AM Leave Daily	
X	141	131	121	111	101	25	23	21	11	3	1			2	4	52	22	24	26	102	112	122	132	142	X	

SPECIAL INSTRUCTIONS

RUN AWAY COAL CARS HAVE PRIORITY
 FLAGMEN MUST BE POSTED AT ALL SWITCHBACKS NORTH OF XINA PASS
 ALL TRAINS MUST REGISTER AT XINA PASS
 SOUTHWARD TRAINS ARE SUPERIOR BY DIRECTION